

# GROOMING & FIELD INSPECTION REPORT



888-524-6017

Field Name: Richard Montgomery High School  
 Address: 250 Richard Montgomery Dr  
 . Rockville, MD 20852  
 Contact Person: Chamy Wijeratne

Annual  Bi Annual  Qtly   
 Bi Monthly  Monthly  Other

Contact Phone # 301-610-8075 / 202-390-7990 Cell

	Grooming Date 3/21/19	Grooming Date 4/17/19	Grooming Date 5/15/19	Grooming Date 6/12/19	Grooming Date	
<b>Lead Tech</b>	Manuel	Manuel	Manuel	Carlos		
<b>Infill Level</b>						<b>Comments</b>
Section 1 Center of the Field	√	√	√	√		
Section 2 East (North) Goal Mouth	√	√	√	√		
Section 3 West (South) Goal Mouth	√	√	√	√		
Section 4 Hash Marks South Side East	√	√	√	√		
Section 5 Hash Marks North Side East	√	√	√	√		
Section 6 Hash Marks South Side West	√	√	√	√		
Section 7 Hash Marks North Side West	√	√	√	√		
Section 8 Penalty Kick East	√	√	√	√		
Section 9 Penalty Kick West	√	√	√	√		

<b>Fiber Wear</b>						<b>Comments</b>
Section 1 Center of the Field	None	None	None	None		
Section 2 East (North) Goal Mouth	None	None	None	None		
Section 3 West (South) Goal Mouth	None	None	None	None		
Section 4 Other	None	None	None	None		

# GROOMING & FIELD INSPECTION REPORT



888-524-6017

Field Name: Richard Montgomery High School  
 Address: 250 Richard Montgomery Dr  
 . Rockville, MD 20852  
 Contact Person: Chamy Wijeratne

Annual  Bi Annual  Qtly   
 Bi Monthly  Monthly  Other

Contact Phone # 301-610-8075 / 202-390-7990 Cell

	Grooming Date 3/21/19	Grooming Date	Grooming Date	Grooming Date	Grooming Date	
Lead Tech	Manuel					
<b>FIELD REPAIRS*</b>	None	None	None	None		Comments
Nailer Board Repairs						
Seams Repaired						
Inlaid Lines Repaired						
Hash Marks Repaired						
Numbers Repaired						
Logo or End Zone Repairs						
Other...						
*See Repair Diagram						
<b>Grooming</b>						
Stand Grooming						
Power Grooming	√	√	√	√		
Deep Clean						

Optional						
Magnet Sweeping						
Spray Disinfection						
Debris Cleaning						
Decompaction Of Infill						
Base Repair						

General Comments:

New field - in great condition groomed & leveled infill and checked edges and high use areas

**GROOMING & FIELD INSPECTION REPORT**



**888-524-6017**

Field Name: Richard Montgomery High School  
Address: 250 Richard Montgomery Dr  
. Rockville, MD 20852  
Contact Person: Chamy Wijeratne

Annual  Bi Annual  Qtly   
Bi Monthly  Monthly  Other

Contact Phone # 301-610-8075 / 202-390-7990 Cell

**GROOMING/REPAIR CERTIFICATE OF COMPLETION**

Definition of Date of Completion

The Date of Completion of the Work represents the date on which GROOMING/REPAIR is completed, per proposal or accepted estimate.

The undersigned has visually inspected the work performed by Sprinturf's personnel or authorized agent, and hereby accepts the work as completed or as otherwise noted and confirms that Sprinturf was on site this day and time.

Date: 6/12/2019

Time: \_\_\_\_\_

Exceptions: \_\_\_\_\_ None \_\_\_\_\_

\_\_\_\_\_  
\_\_\_\_\_

**Sprinturf Representative**

**BY:**

**Print Name:** Carlos

**Title:** Lead Tech

**Signature:** \_\_\_\_\_ Carlos

**Authorized Representative**

**BY:**

**Print Name:** \_\_\_\_\_

**Title:** \_\_\_\_\_

**Signature:** \_\_\_\_\_